

**Office of The Sub Division Officer
PWD Distt. Sub Division No.1, Indore**

S.No. 530

/SAC/2026-27

Date: 3/8/26


BUILDING SAFETY CERTIFICATE

It is certified that the existing building **St. Norbert School at Rangwasa, Cat Rau Road, Indore (M.P.)** is having block(s) /Floor(s) as per details below:

Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G + 3	G+3				

The building is owned/occupied by **St. Norbert School** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Work Department Sub Division No.1, Indore (MP)** (Name of Department/Govt.) on **03/08/2026** (date of inspection) in the presence of **Manager Fr. Simon Raj, Indore** and that the building/premises is fit for occupancy for running school with effect from **03/08/2026** for a period of 01 years in accordance with rule and subject to compliance of the specific conditions as appended.

Issued on **03/08/2026** at Indore by Sub Divisional Officer PWD, Indore.



Signature: *Fr. S. SH*



Signature of Sub Division Officer: *[Signature]*
Sub Division Officer
PWD Distt. Sub Division No.1, Indore
~~Sub Divisional Officer~~
P.W.D. (B&T) Dist. Sub Dn. No. 1, INDORE